

**79-34,101. Measurement, calibration and marking of containers.** The director may require that all tanks or other containers in which L-P gas, as defined by this act, is transported be accurately measured, calibrated and marked.

**History:** L. 1959, ch. 405, § 12; July 1.